

**Flood Control Project Maintenance
Levee Inspections**

Fall 2016 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

NA0003	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.					
Butte County Department of Public Works	M *	23.78						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	0.25		0.25	1.05%	0.17	0.14		
Trim / Thin Trees	0.64	0.04	0.80	3.36%				
Encroachments					0.56	0.59		
Animal Control	0.01		0.01	0.04%				
Slope Stability	0.06		0.06	0.25%				
<i>Supplemental</i>								
2015 USACE Erosion Survey, DRAFT	0.06		0.06	0.25%				
DWR UCIP Field Study					0.49			
<i>LMA Totals:</i>	1.02	0.04	1.18	4.96% *	1.22	0.73	0.00	0.00
Unit No. 01 Mud Creek RB	Overall Unit Rating	Total Unit Miles						
NA0003	A	6.80						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	0.02		0.02	0.29%	0.16	0.14		
Trim / Thin Trees	0.01		0.01	0.15%				
Encroachments					0.25	0.09		
Animal Control	0.01		0.01	0.15%				
<i>Supplemental</i>								
2015 USACE Erosion Survey, DRAFT	0.06		0.06	0.88%				
DWR UCIP Field Study					0.10			
<i>Unit Totals:</i>	0.10	0.00	0.10	1.47%	0.51	0.23	0.00	0.00
Unit No. 02 Mud Creek LB	Overall Unit Rating	Total Unit Miles						
NA0003	A	7.96						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	0.06		0.06	0.75%	0.01			
Trim / Thin Trees	0.20		0.20	2.51%				
Encroachments					0.08	0.32		
Slope Stability	0.02		0.02	0.25%				
<i>Supplemental</i>								
DWR UCIP Field Study					0.19			
<i>Unit Totals:</i>	0.28	0.00	0.28	3.52%	0.28	0.32	0.00	0.00
Unit No. 02A Channel Slough LB	Overall Unit Rating	Total Unit Miles						
NA0003	A	0.26						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
No Items								
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%				

**Flood Control Project Maintenance
Levee Inspections**

Fall 2016 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 03 Sycamore and Sheep Hollow Creeks RB	Overall Unit Rating	Total Unit Miles						
NA0003	A	4.05						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	0.01		0.01	0.25%				
Trim / Thin Trees	0.01		0.01	0.25%				
Slope Stability	0.02		0.02	0.49%				
<i>Supplemental</i>								
DWR UCIP Field Study					0.09			
<i>Unit Totals:</i>	0.04	0.00	0.04	0.99%	0.09	0.00	0.00	0.00

Unit No. 04 Sycamore and Dry Creeks RB	Overall Unit Rating	Total Unit Miles						
NA0003	M	2.86						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	0.03		0.03	1.05%				
Trim / Thin Trees	0.10	0.04	0.26	9.08%				
Encroachments					0.21	0.18		
<i>Supplemental</i>								
DWR UCIP Field Study					0.10			
<i>Unit Totals:</i>	0.13	0.04	0.29	10.13%	0.31	0.18	0.00	0.00

Unit No. 05 Big Chico Diversion LB	Overall Unit Rating	Total Unit Miles						
NA0003	U	1.85						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	0.13		0.13	7.04%				
Trim / Thin Trees	0.32		0.32	17.34%				
Encroachments					0.02			
Slope Stability	0.02		0.02	1.08%				
<i>Supplemental</i>								
DWR UCIP Field Study					0.01			
<i>Unit Totals:</i>	0.47	0.00	0.47	25.47%	0.03	0.00	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2016 Levee Inspection Results

Butte County Department of Public Works

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)			M *	

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

* Overall LMA Threshold Percent is less than
10.00%; however, U Rated Miles are present,
so the Overall LMA Rating is M instead of A.

† SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Butte County Department of Public Works

Waterway			Bank	Unit Miles
Unit No. 01 Mud Creek			Right	6.80
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	4/25/2016 - 4/25/2016		10/13/2016 - 10/13/2016	
DWR Inspector	Keith Millard		Tariq Chechi	
Accompanied By	Shawn Bates Butte County		Shawn Bates Butte County	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start		Rating **	A	Issue No.	2
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_NA0003_01_s_2013_2				
Comment Code					
Inspector Comment					
The LMA has adequate flood fight supplies and equipment.					

No Photos

LM Start		Rating **	A	Issue No.	6
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_NA0003_01_s_2013_6				
Comment Code					
Inspector Comment					
The LMA completed flood fight training in 2016.					

No Photos

LM Start		Rating **	A	Issue No.	10
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_NA0003_01_s_2013_10				
Comment Code					
Inspector Comment					
The LMA has the O&M manuals.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	1.00	Rating **	M	Issue No.	56
LM End	1.00	Issue Type +	En	Location *	N/A
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.739268 °	39.739268 °
				-121.931891 °	-121.931891 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32044 DS_ID:19211 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Vegetation debris on waterside. Needs clearing and cleaning. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 12.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 2/20/2014					

LM Start	1.00	Rating **	M	Issue No.	56 (cont)
LM End	1.00	Issue Type +	En	Location *	N/A

Photo 1 of 2 : UCIP_FA_2016_32044_58543.jpg



WS view: U typed concrete headwall, pipe, and flapgate on levee slope.

Photo 2 of 2 : UCIP_FA_2016_32044_58542.jpg



WS view: vegetation debris blocking outlet.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Butte County Department of Public Works

View of the firewood along the landside toe.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	1.97	Rating **	M	Issue No.	42
LM End	1.99	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.747946 °	39.748170 °
				-121.918881 °	-121.918778 °
DWR ID	DWR_NA0003_01_s _ 2016_42				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Landscaping vegetation obscuring visibility on the landside toe.					

A photograph showing a gravel driveway or parking area. On the left, the rear of a white vehicle is partially visible. To the right, there is a dense, tall green hedge or bush. The ground is covered in gravel and some dry leaves. The scene is brightly lit, suggesting a sunny day.

View of the overgrown trees at the landside levee toe.

LM Start	2.00	Rating **	M	Issue No.	3
LM End	2.04	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.748330 °	39.748867 °
				-121.918685 °	-121.918533 °
DWR ID	DWR_NA0003_01_s _ 2012_3				
Comment Code					
FE : Fence					
Inspector Comment					

A gravel driveway leads to a yellow house with a satellite dish. The house is partially obscured by trees and a wooden fence. A satellite dish is visible in the foreground on the left side of the driveway. The driveway is made of gravel and dirt, and the house is yellow with a dark roof. There are trees and a wooden fence in the background.

View of the fences along the landside toe.

LM Start	2.03	Rating **	M	Issue No.	48
LM End	2.11	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.748784 °	39.749872 °
				-121.918597 °	-121.918296 °
DWR ID	DWR_NA0003_01_f_2016_48				
Comment Code					
V6 : Landscaping					
Inspector Comment					

View of landscaping vegetation blocking visibility.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.04	Rating **	M	Issue No.	47
LM End	2.05	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.748797 °	39.749034 °
				-121.918592 °	-121.918526 °
DWR ID	DWR_NA0003_01_f_2016_47				
Comment Code					
FE : Fence					
Inspector Comment					

No Photos

LM Start	2.06	Rating **	U	Issue No.	40
LM End	2.08	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.749145 °	39.749461 °
				-121.918506 °	-121.918425 °
DWR ID	DWR_NA0003_01_s_2016_40				
Comment Code					
FE : Fence					
Inspector Comment					
Piecemeal corrugated fencing with vegetation completely obscuring landside toe. Small fort included along fencing.					

Photo 1 of 1 : FA_2016_NA0003_64_40_20160823_00024.jpg



View of a metal fence and treehouse obstructing visibility and access.

LM Start	2.06	Rating **	U	Issue No.	41
LM End	2.06	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.749149 °	39.749149 °
				-121.918510 °	-121.918510 °
DWR ID	DWR_NA0003_01_s_2016_41				
Comment Code					
DE : Debris					
Inspector Comment					
Homeowner is dragging soil and debris across levee and dumping on waterside terrace.					

Photo 1 of 2 : FA_2016_NA0003_64_41_20160823_00025.jpg



04/25/2016: Soil and debris dragged across levee from L/S to W/S.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Butte County Department of Public Works

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.60	Rating **	C	Issue No.	26
LM End	2.60	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.756022 °	39.756022 °
				-121.914788 °	-121.914788 °
DWR ID	DWR_NA0003_01_f_2014_26				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside slope.					

No Photos

LM Start	2.71	Rating **	M	Issue No.	58
LM End	2.71	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.757445 °	39.757445 °
				-121.913654 °	-121.913654 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30291 DS_ID:19230 EP_NO: 16633 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: A concrete water control box on landside shoulder.It needs confirmation and more info from LMA and/or DWR Inspector. FIELD_STRUCT_DESC: A 2-inch diameter storm water discharge pipeline through the right bank and landward levee toe of Mud Creek. Used a 2-inch coated & wrapped steel pipe. Submerged pump in 36 inch dia CMP casing approx 10 ft from landside toe. Drainage ditch, up to 4 ft wide, runs perpendicular to levee alignment starting at CMP riser and running away from levee. (App. No. 16633) FS Date: 2/20/2014					

Photo 1 of 2 : UCIP_FA_2016_30291_55700.jpg



LS view: CMP riser on levee toe (top) and control box on levee shoulder (bottom).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.71	Rating **	M	Issue No.	58 (cont)	
LM End	2.71	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.757445 °		39.757445 °
				-121.913654 °		-121.913654 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:30291						
DS_ID:19230						
EP_NO: 16633						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: A concrete water control box on landside shoulder.It needs confirmation and more info from LMA and/or DWR Inspector.						
FIELD_STRUCT_DESC: A 2-inch diameter storm water discharge pipeline through the right bank and landward levee toe of Mud Creek.						
Used a 2-inch coated & wrapped steel pipe. Submerged pump in 36 inch dia CMP casing approx 10 ft from landside toe. Drainage ditch, up to 4 ft wide, runs perpendicular to levee alignment starting at CMP riser and running away from levee. (App. No. 16633)						
FS Date: 2/20/2014						

Photo 2 of 2 : UCIP_FA_2016_30291_55699.jpg



LS view: CMP riser on levee toe and drainage ditch perpendicular to the levee.

LM Start	2.93	Rating **	M	Issue No.	1
LM End	2.93	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.759755 °	39.759755 °
				-121.911160 °	-121.911160 °
DWR ID	DWR_NA0003_01_s_2012_1				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside slope.					

Photo 1 of 1 : FA_2016_NA0003_64_1_20160823_00001.jpg



View of the pruning pile along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Levee Inspection Report By Mile - Fall 2016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

Photo 1 of 1 : FA_2016_NA0003_64_39_20160823_00023.jpg



View of equipment and vehicles along the landside toe.

Photo 1 of 1 : FA_2016_NA0003_64_25_20161019_00056.jpg



View of the prunings and wooden posts along the landside toe.

Thursday, December 08, 2016 11:06 **FINAL DATA** Page 9 of 27

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.03	Rating **	M	Issue No.	59
LM End	3.03	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.761224 °	39.761224 °
				-121.911108 °	-121.911108 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:30294
DS_ID:19216
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Inlet and outlet needs cleaning and clearing of debris.
FIELD_STRUCT_DESC: 24-inch CM pipe through levee, 8.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.
FS Date: 2/20/2014

LM Start	3.03	Rating **	M	Issue No.	59 (cont)
LM End	3.03	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_30294_55704.jpg



WS view: U type concrete headwall, flapgate on levee slope.

Photo 2 of 2 : UCIP_FA_2016_30294_55703.jpg



LS view: U type concrete headwall and CMP on levee slope. Debris blocking the inlet pipe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.15	Rating **	M	Issue No.	31
LM End	3.15	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.762565 °	39.762565 °
				-121.909873 °	-121.909873 °
DWR ID	DWR_NA0003_01_s_ 2015_31				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside slope.					

LM Start	3.15	Rating **	M	Issue No.	31 (cont)
LM End	3.15	Issue Type +	En	Location *	LS

Photo 1 of 2 : FA_2016_NA0003_64_31_20160823_00015.jpg



View of the prunings along the landside slope.

Photo 2 of 2 : FA_2016_NA0003_64_31_20160823_00016.jpg



View of the prunings and bait station along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.18	Rating **	M	Issue No.	60
LM End	3.18	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.763067 °	39.763067 °
				-121.909608 °	-121.909608 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30295					
DS_ID:19217					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: It needs cleaning and clearing in inlet and outlet ends.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 9.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end.					
Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/20/2014					

LM Start	3.18	Rating **	M	Issue No.	60 (cont)
LM End	3.18	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_30295_55706.jpg



WS view: U type concrete headwall, flapgate on levee slope. Vegetation debris blocking the outlet.

Photo 2 of 2 : UCIP_FA_2016_30295_55705.jpg



LS view: U type concrete headwall and CMP on levee slope. Vegetation debris blocking the inlet.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.25	Rating **	M	Issue No.	27
LM End	3.25	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.763993 °	39.763993 °
				-121.909108 °	-121.909108 °
DWR ID	DWR_NA0003_01_f_2014_27				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside slope.					

Photo 1 of 1 : FA_2016_NA0003_64_27_20160823_00011.jpg



View of the prunings along the landside toe.

LM Start	3.39	Rating **	M	Issue No.	61
LM End	3.39	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.765440 °	39.765440 °
				-121.907261 °	-121.907261 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30310					
DS_ID:19218					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing of debris.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 10.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/20/2014					

Photo 1 of 2 : UCIP_FA_2016_30310_55741.jpg



WS view: U type concrete headwall, pipe, and flapgate on levee slope.
Vegetation debris blocking outlet.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Levee Inspection Report By Mile - Fall 2016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.39	Rating **	M	Issue No.	61 (cont)	
LM End	3.39	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.765440 °	39.765440 °	
				-121.907261 °	-121.907261 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:30310 DS_ID:19218 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs cleaning and clearing of debris. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 10.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 2/20/2014						

A photograph showing a concrete drainage ditch or culvert. The ditch is made of concrete and has a circular opening at the bottom. The area around the ditch is covered with dry grass and soil. The ditch appears to be in a rural or undeveloped area.

LS view: U type concrete headwall and CMP on levee slope.

LM Start	3.70	Rating **	M	Issue No.	50
LM End	3.70	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.767920 °	39.767920 °
				-121.902520 °	-121.902520 °
DWR ID	DWR_NA0003_01_f_2016_50				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from the landside toe.					

A photograph showing a large, dense pile of dry brush and sticks on a dirt road shoulder. The pile is composed of various types of dry vegetation, including branches and leaves. In the background, there are several green trees and a utility pole. The ground is dry and dusty. A date stamp '10/19/2016' is visible in the bottom right corner of the image.

View of the prunings along the landside toe.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.88	Rating **	M	Issue No.	32
LM End	3.88	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.770292 °	39.770292 °
				-121.901428 °	-121.901428 °
DWR ID	DWR_NA0003_01_f_2015_32				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside toe.					

Photo 1 of 1 : FA_2016_NA0003_64_32_20160823_00017.jpg



View of the prunings along the landside toe.

LM Start	3.97	Rating **	M	Issue No.	62
LM End	3.97	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.771293 °	39.771293 °
				-121.900247 °	-121.900247 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30311 DS_ID:19219 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs cleaning and clearing of debris in both ends of the pipe. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 9.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 2/20/2014					

Photo 1 of 2 : UCIP_FA_2016_30311_55743.jpg



WS view: U type concrete headwall, pipe, and flapgate on levee slope. Vegetation debris blocking outlet.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.97	Rating **	M	Issue No.	62 (cont)	
LM End	3.97	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.771293 °		39.771293 °
				-121.900247 °		-121.900247 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:30311 DS_ID:19219 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs cleaning and clearing of debris in both ends of the pipe. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 9.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 2/20/2014						

Photo 2 of 2 : UCIP_FA_2016_30311_55742.jpg



LS view: U type concrete headwall and CMP on levee slope.

LM Start	4.01	Rating **	M	Issue No.	29
LM End	4.01	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.771732 °	39.771732 °
				-121.899699 °	-121.899699 °
DWR ID	DWR_NA0003_01_f_2014_29				
Comment Code					
CR : Crops					
Inspector Comment					
Fruit trees at the toe of the levee.					

Photo 1 of 1 : FA_2016_NA0003_64_29_20161019_00058.jpg



View of the fruit trees within 10' of landside levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	4.03	Rating **	M	Issue No.	51
LM End	4.03	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.771877 °	39.771877 °
				-121.899441 °	-121.899441 °
DWR ID	DWR_NA0003_01_f_2016_51				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_64_51_20161019_00059.jpg



View of the rodent holes along the landside slope.

LM Start	4.06	Rating **	M	Issue No.	52
LM End	4.06	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.772051 °	39.772051 °
				-121.898974 °	-121.898974 °
DWR ID	DWR_NA0003_01_f_2016_52				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from the landside toe.					

Photo 1 of 1 : FA_2016_NA0003_64_52_20161019_00060.jpg



View of the prunings along the landside toe.

LM Start	4.26	Rating **	M	Issue No.	5
LM End	4.32	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.773257 °	39.773969 °
				-121.895618 °	-121.895078 °
DWR ID	DWR_NA0003_01_s_2016_5				
Comment Code					
Inspector Comment					
2011 - Two large erosion scallops at the toe from a rotational failure. Deep cracks along the slope indicate the potential for further failures. 2015: Site is part of the extended inventory, last inspected 2011. [2015 Site ID: MUD_4-4_R]					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

Butte County Department of Public Works

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	4.46	Rating **	M	Issue No.	63
LM End	4.46	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.775905 °	39.775905 °
				-121.893980 °	-121.893980 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30312					
DS_ID:19220					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing of debris.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 13.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/20/2014					

LM Start	4.46	Rating **	M	Issue No.	63 (cont)
LM End	4.46	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_30312_55745.jpg



WS view: U type concrete headwall, pipe, and flapgate on levee slope. Vegetation debris blocking outlet.

Photo 2 of 2 : UCIP_FA_2016_30312_55744.jpg



LS view: U type concrete headwall and CMP on levee slope. Needs cleaning and clearing of debris.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Butte County Department of Public Works

View of prunings and stumps at the landside toe.

Page 20 of 27

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	4.81	Rating **	M	Issue No.	57
LM End	4.81	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.780244 °	39.780244 °
				-121.891267 °	-121.891267 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30388					
DS_ID:19221					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: CM Standpipe intake. Intake pipe with air vent. Steel rib-bar grit cover on the standpipe on landside levee toe.Needs cleaning and clearing on both ends of the pipe.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 15.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on waterside ends. Grouted riprap spillway on the waterward end. CM Standpipe intake. Intake pipe with air vent. Steel rib-bar grit cover on the standpipe on landside levee toe. O&M Manual Sac 504, May 1965.					
FS Date: 2/20/2014					


LM Start	4.81	Rating **	M	Issue No.	57 (cont)
LM End	4.81	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_30388_55891.jpg



WS view: U type concrete headwall, pipe, and flapgate on levee slope. Vegetation/soil debris blocking outlet.

Photo 2 of 2 : UCIP_FA_2016_30388_55890.jpg



LS view: Underground CM standpipe intake with steel grit on levee toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	5.06	Rating **	M	Issue No.	65
LM End	5.06	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.783387 °	39.783387 °
				-121.888839 °	-121.888839 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41870					
DS_ID:19231					
EP_NO: 9874					
Repair Type: Non-Urgent					
Crossing Status: Indicator Found					
UCIP Comments: Need to contact the owner to determine crossing status and install gasoline markers if its appropriate to do so.					
FIELD_STRUCT_DESC: Install a 6-inch gas main thru both levees and channel of Mud Creek Downstream from old Hwy 99E. (Permit No. 9874) gasoline indicator/marker post found across the creek on NA 3 Unit 2.					
FS Date: 2/20/2014					

No Photos

LM Start	5.20	Rating **	U	Issue No.	55
LM End	5.20	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.784234 °	39.784234 °
				-121.886589 °	-121.886589 °
DWR ID	DWR_NA0003_01_f_2016_55				
Comment Code					
V6 : Landscaping					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_64_55_20161019_00062.jpg



View of the blackberries blocking visibility and access.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	5.30	Rating **	M	Issue No.	64
LM End	5.30	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.784739 °	39.784739 °
				-121.884860 °	-121.884860 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:30368
DS_ID:19223
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 12-inch steel pipe about 14 ft below the crown.
FIELD_STRUCT_DESC: 12-inch steel pipeline through levee, 14-ft below the crown. Slide gate in concrete box on waterward slope. Flap gate on waterward side. Grouted rock revetment on waterward slope. Three pumps on concrete pad on landside.
FS Date: 2/24/2014

LM Start	5.30	Rating **	M	Issue No.	64 (cont)
LM End	5.30	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_30368_55861.jpg



WS view: slide gate in concrete box on levee slope.

Photo 2 of 2 : UCIP_FA_2016_30368_55860.jpg



WS view: concrete headwall and flapgate on levee slope.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	5.65	Rating **	M	Issue No.	45
LM End	5.65	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.789145 °	39.789145 °
				-121.886548 °	-121.886548 °
DWR ID	DWR_NA0003_01_f_2016_45				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from the landside toe.					

No Photos

LM Start	5.89	Rating **	M	Issue No.	44
LM End	5.89	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.792121 °	39.792121 °
				-121.886836 °	-121.886836 °
DWR ID	DWR_NA0003_01_f_2016_44				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Blackberry bramble					

No Photos

LM Start	5.91	Rating **	M	Issue No.	43
LM End	5.91	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.792482 °	39.792482 °
				-121.887078 °	-121.887078 °
DWR ID	DWR_NA0003_01_f_2016_43				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Blackberry bramble					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	5.96	Rating **	M	Issue No.	22
LM End	5.96	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.793116 °	39.793116 °
				-121.887296 °	-121.887296 °
DWR ID	DWR_NA0003_01_f_2016_22				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Blackberry bramble					

Photo 1 of 1 : FA_2016_NA0003_64_22_20161019_00063.jpg



View of the blackberries blocking visibility and access.

LM Start	5.98	Rating **	U	Issue No.	37
LM End	6.07	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.793411 °	39.794580 °
				-121.887310 °	-121.886759 °
DWR ID	DWR_NA0003_01_s_2016_37				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Various overgrown vegetation completely obscuring landside toe visibility.					

Photo 1 of 1 : FA_2016_NA0003_64_37_20160823_00021.jpg



04/25/2016: Trim trees on L/S slope.

LM Start	6.08	Rating **	M	Issue No.	36
LM End	6.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.794708 °	39.794708 °
				-121.886616 °	-121.886616 °
DWR ID	DWR_NA0003_01_s_2016_36				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Blackberry bramble					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	6.09	Rating **	U	Issue No.	35
LM End	6.13	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.794875 °	39.795179 °
				-121.886394 °	-121.885835 °
DWR ID	DWR_NA0003_01_s _ 2016_35				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Bamboo vegetation along landside toe blocking visibility.					

A gravel road curves through a dense forest of tall, green trees. The road is made of light-colored gravel and leads into the distance, flanked by lush green foliage. The sky is visible in the background, showing a clear blue color.

View of bamboo blocking visibility and access.

LM Start	6.16	Rating **	M	Issue No.	34
LM End	6.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.795428 °	39.795428 °
				-121.885306 °	-121.885306 °
DWR ID	DWR_NA0003_01_s_2016_34				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Blackberry bramble on landside toe blocking visibility.					

A gravel driveway leads from the foreground towards a house in the background. The driveway is bordered on the right by a dense, green hedge. A wooden fence runs along the edge of the property behind the hedge. The house is partially visible in the distance, surrounded by trees and greenery.

Trim vegetation at L/S toe.

LM Start	6.36	Rating **	M	Issue No.	30
LM End	6.39	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.797714 °	39.797884 °
				-121.883384 °	-121.882883 °
DWR ID	DWR_NA0003_01_s_2016_30				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Rosemary landscaping covering landside toe.					

A photograph showing a gravel driveway or road. On the left side, there is a dense line of green shrubs and trees, including a large weeping willow. A portion of a house with a grey roof is visible behind the foliage. To the right of the gravel path is a dry, open field with sparse vegetation. The sky is overcast. A date stamp '10/13/2018' is located in the bottom right corner of the image.

View of the landscaping blocking visibility.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Mud Creek	Right	6.80	10/13/2016 10/13/2016	Tariq Chechi

LM Start	6.43	Rating **	U	Issue No.	28
LM End	6.47	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.798166 °	39.798492 °
				-121.882236 °	-121.881722 °
DWR ID	DWR_NA0003_01_s _ 2016_28				
Comment Code					
FE : Fence					
Inspector Comment					
6' high wooden fencing at landside toe.					

Photo 1 of 1 : FA_2016_NA0003_64_28_20160823_00012.jpg



View of the fence blocking visibility and access along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Butte County Department of Public Works

Waterway			Bank	Unit Miles
Unit No. 02 Mud Creek			Left	7.96
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	4/25/2016 - 4/25/2016		10/13/2016 - 10/13/2016	
DWR Inspector	Keith Millard		Tariq Chechi	
Accompanied By			Shawn Bates Butte County	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.23	Rating **	M	Issue No.	55
LM End	0.23	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.797416 °	39.797416 °
				-121.881675 °	-121.881675 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:31667
DS_ID:19234
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Needs cleaning and clearing the culvert.
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 6.6 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap spillway on the waterward end.
O&M Manual Sac 504, May 1965.
FS Date: 3/11/2014

LM Start	0.23	Rating **	M	Issue No.	55 (cont)
LM End	0.23	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_31667_57968.jpg



WS view: CMP culvert with U type concrete headwall. Vegetation debris blocking outlet box.

Photo 2 of 2 : UCIP_FA_2016_31667_57967.jpg



WS view: U type concrete headwall, pipe, and flapgate on levee slope. Vegetation debris on outlet box.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.31	Rating **	M	Issue No.	29
LM End	0.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.797071 °	39.797071 °
				-121.883049 °	-121.883049 °
DWR ID	DWR_NA0003_02_f_2016_29				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_65_29_20161019_00015.jpg



View of the slope instability caused by vehicles along the landside slope.

LM Start	1.26	Rating **	M	Issue No.	41
LM End	1.26	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.784062 °	39.784062 °
				-121.884344 °	-121.884344 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30403					
DS_ID:19235					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing of debris.					
FIELD_STRUCT_DESC: 24-inch CM pipe through levee, 12.5 below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/24/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	1.45	Rating **	M	Issue No.	30
LM End	1.45	Issue Type +	En	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.783084 °	39.783084 °
				-121.887625 °	-121.887625 °
DWR ID	DWR_NA0003_02_f_2016_30				
Comment Code					
V6 : Landscaping					
Inspector Comment					
Blackberry bramble					

Photo 1 of 1 : FA_2016_NA0003_65_30_20161019_00016.jpg



View of the blackberries blocking visibility and access.

LM Start	1.46	Rating **	M	Issue No.	48
LM End	1.46	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.782980 °	39.782980 °
				-121.887834 °	-121.887834 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30743					
DS_ID:19237					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing of debris.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 11.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/24/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	1.49	Rating **	U	Issue No.	3
LM End	1.81	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.782773 °	39.778972 °
				-121.888178 °	-121.891563 °
DWR ID	DWR_NA0003_02_s_2012_3				
Comment Code					
FE : Fence					
Inspector Comment					
The fence is within the easement.					

Photo 1 of 1 : FA_2016_NA0003_65_3_20160823_00002.jpg



View of the fence along the landside toe of the levee.

LM Start	1.49	Rating **	M	Issue No.	56
LM End	1.49	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.782766 °	39.782766 °
				-121.888187 °	-121.888187 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41873 DS_ID:24803 EP_NO: 9874 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: May need to contact owner to determine status of crossing and install markers as appropriate. FIELD_STRUCT_DESC: A 6-inch gas main through both levees and channel of Mud Creek Downstream from old Highway 99E (Esplanade Road Bridge). (Permit No. 9874- PG and E) Indicator on landside toe. FS Date: 2/24/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	1.54	Rating **	M	Issue No.	31
LM End	1.74	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.782175 °	39.779667 °
				-121.888813 °	-121.890613 °
DWR ID	DWR_NA0003_02_f_2016_31				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_65_31_20161019_00017.jpg



View of the trees along the landside toe.

LM Start	1.62	Rating **	N	Issue No.	32
LM End	1.62	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.781173 °	39.781173 °
				-121.889526 °	-121.889526 °
DWR ID	DWR_NA0003_02_f_2016_32				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.03	Rating **	M	Issue No.	57
LM End	2.03	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.776025 °	39.776025 °
				-121.892911 °	-121.892911 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41375 DS_ID:19238 EP_NO: 12619A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: - 24-inch CM pipe.- inlet and spillway may need cleaning and clearing. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 11.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwall on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. (App. 12619 - Vermillion). Replaced 24-inch pipe with 36-inch pipe. 3/79 (App.12619A) FS Date: 2/24/2014					

No Photos

LM Start	2.34	Rating **	M	Issue No.	49
LM End	2.34	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.772185 °	39.772185 °
				-121.895681 °	-121.895681 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30763 DS_ID:19239 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Debris in landside inlet area. Needs cleaning and clearing of debris. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 10.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 2/24/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.74	Rating **	M	Issue No.	50
LM End	2.74	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.768741 °	39.768741 °
				-121.901176 °	-121.901176 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30783					
DS_ID:19240					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing of debris.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 10.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/24/2014					

No Photos

LM Start	2.80	Rating **	M	Issue No.	1
LM End	2.80	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.767841 °	39.767841 °
				-121.901534 °	-121.901534 °
DWR ID	DWR_NA0003_02_f_2013_1				
Comment Code					
FW : Firewood					
Inspector Comment					
Remove firewood and broken concrete pipes from the landside toe.					

Photo 1 of 1 : FA_2016_NA0003_65_1_20161019_00018.jpg



View of the firewood and broken concrete pipes along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.31	Rating **	M	Issue No.	5
LM End	3.31	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.763208 °	39.763208 °
				-121.908517 °	-121.908517 °
DWR ID	DWR_NA0003_02_f_2012_5				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_65_5_20160823_00003.jpg



View of the brush pile along landside toe.

LM Start	3.50	Rating **	M	Issue No.	51
LM End	3.50	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.760847 °	39.760847 °
				-121.910265 °	-121.910265 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:30803					
DS_ID:19241					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing of debris.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 6.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/24/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.52	Rating **	M	Issue No.	10
LM End	3.52	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.760582 °	39.760582 °
				-121.910303 °	-121.910303 °
DWR ID	DWR_NA0003_02_f_2015_10				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_65_10_20160823_00006.jpg



View of the vehicle erosion along the landside slope.

LM Start	3.95	Rating **	M	Issue No.	33
LM End	3.95	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.755681 °	39.755681 °
				-121.910628 °	-121.910628 °
DWR ID	DWR_NA0003_02_f_2016_33				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from the landside toe.					

Photo 1 of 1 : FA_2016_NA0003_65_33_20161019_00019.jpg



View of the prunings along the landside toe.

LM Start	4.42	Rating **	A/W	Issue No.	11
LM End	4.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.751120 °	39.751120 °
				-121.915977 °	-121.915977 °
DWR ID	DWR_NA0003_02_f_2015_11				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	4.54	Rating **	M	Issue No.	34
LM End	4.54	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.749708 °	39.749708 °
				-121.917162 °	-121.917162 °
DWR ID	DWR_NA0003_02_f_2016_34				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from the landside toe.					

Photo 1 of 1 : FA_2016_NA0003_65_34_20161019_00020.jpg



View of the prunings along the landside toe.

LM Start	4.55	Rating **	A/W	Issue No.	8
LM End	4.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.749639 °	39.749639 °
				-121.917188 °	-121.917188 °
DWR ID	DWR_NA0003_02_f_2013_8				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Butte County has been grouting the rodent holes.					

Photo 1 of 2 : FA_2016_NA0003_65_8_20160823_00004.jpg



View of the bait station placed by the rodent hole.

LM Start	4.55	Rating **	A/W	Issue No.	8 (cont)
LM End	4.55	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA_2016_NA0003_65_8_20160823_00005.jpg



View of the bait station by the rodent holes.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	4.61	Rating **	M	Issue No.	52
LM End	4.61	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.748731 °	39.748731 °
				-121.917577 °	-121.917577 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31028					
DS_ID:19245					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing of debris.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 10.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/25/2014					

LM Start	4.61	Rating **	M	Issue No.	52 (cont)
LM End	4.61	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_31028_56913.jpg



WS view: U type concrete headwall, pipe, and flapgate on levee slope.
Soil/mud on outlet box.

Photo 2 of 2 : UCIP_FA_2016_31028_56912.jpg



LS view: U type concrete headwall and CMP on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	5.64	Rating **	M	Issue No.	53
LM End	5.64	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.738898 °	39.738898 °
				-121.930242 °	-121.930242 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31031					
DS_ID:19247					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing of debris.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 11.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/25/2014					

No Photos

LM Start	6.07	Rating **	M	Issue No.	35
LM End	6.07	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.733583 °	39.733583 °
				-121.930511 °	-121.930511 °
DWR ID	DWR_NA0003_02_f_2016_35				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from the landside toe.					

Photo 1 of 1 : FA_2016_NA0003_65_35_20161019_00021.jpg



View of the prunings along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	6.08	Rating **	M	Issue No.	36
LM End	6.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.733503 °	39.733503 °
				-121.930481 °	-121.930481 °
DWR ID	DWR_NA0003_02_f_2016_36				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_65_36_20161019_00022.jpg



View of the dense vegetation along the landside toe.

LM Start	6.09	Rating **	M	Issue No.	58
LM End	6.09	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.733297 °	39.733297 °
				-121.930411 °	-121.930411 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41376 DS_ID:19248 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs cleaning and clearing of debris. FIELD_STRUCT_DESC: 1 of 2: Two 42-inch CM pipes through the levee, 16.0 feet below the crown. Flap gates on the waterward end. Slide gates in CM pipe riser on the waterward slope. Concrete "U" headwalls on both ends. Grouted riprap apron and rock revetment on the landward end. Channel Slough drainage structure. O&M Manual Sac 504, May 1965. FS Date: 2/25/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	6.09	Rating **	M	Issue No.	59
LM End	6.09	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.733280 °	39.733280 °
				-121.930409 °	-121.930409 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41377 DS_ID:19259 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs cleaning and clearing of debris. FIELD_STRUCT_DESC: 2 of 2: Two 42-inch CM pipes through the levee, 16.0 feet below the crown. Flap gates on the waterward end. Slide gates in CM pipe riser on the waterward slope. Concrete "U" headwalls on both ends. Grouted riprap apron and rock revetment on the landward end. Channel Slough drainage structure. O&M Manual Sac 504, May 1965. FS Date: 2/25/2014					

No Photos

LM Start	6.15	Rating **	M	Issue No.	54
LM End	6.15	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.732515 °	39.732515 °
				-121.930373 °	-121.930373 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31034					
DS_ID:19249					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing of debris.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 12.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/25/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	6.36	Rating **	C	Issue No.	12
LM End	6.36	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.729663 °	39.729663 °
				-121.931883 °	-121.931883 °
DWR ID	DWR_NA0003_02_f_2015_12				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove the prunings from the landside toe.					

No Photos

LM Start	6.43	Rating **	M	Issue No.	42
LM End	6.43	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.728812 °	39.728812 °
				-121.932623 °	-121.932623 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31085 DS_ID:19251 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs cleaning and clearing of debris. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 15.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 2/25/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Butte County Department of Public Works

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	6.94	Rating **	M	Issue No.	43
LM End	6.94	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.722798 °	39.722798 °
				-121.937828 °	-121.937828 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31103					
DS_ID:19252					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing of debris.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 15.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 2/25/2014					

No Photos

LM Start	7.17	Rating **	M	Issue No.	40
LM End	7.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.719593 °	39.718933 °
				-121.938137 °	-121.937635 °
DWR ID	DWR_NA0003_02_f_2016_40				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_65_40_20161019_00027.jpg



View of the dense vegetation along the landside toe blocking visibility and access.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	7.22	Rating **	M	Issue No.	45
LM End	7.22	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.718882 °	39.718882 °
				-121.937602 °	-121.937602 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32085 DS_ID:19253 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Slide gates in CMP risers on waterside shoulder.Needs cleaning and clearing of debris. FIELD_STRUCT_DESC: 1 of 3: Three 48-inch CM pipes through levee, 18.0 feet below crown. Flap gate on the waterward end. Slide gate in CMP riser on waterside shoulder. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 2/25/2014					

No Photos

LM Start	7.23	Rating **	M	Issue No.	46
LM End	7.23	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.718862 °	39.718862 °
				-121.937594 °	-121.937594 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32086 DS_ID:19260 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Slide gates in CMP risers on waterside shoulder.Needs cleaning and clearing of debris. FIELD_STRUCT_DESC: 2 of 3: Three 48-inch CM pipes through levee, 18.0 feet below crown Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 2/25/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Mud Creek	Left	7.96	10/13/2016 10/13/2016	Tariq Chechi

LM Start	7.23	Rating **	M	Issue No.	47
LM End	7.23	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.718849 °	39.718849 °
				-121.937580 °	-121.937580 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32087 DS_ID:19261 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Slide gates in CMP risers on waterside shoulder.Needs cleaning and clearing on both pipe ends. FIELD_STRUCT_DESC: 3 of 3: Three 48-inch CM pipes through levee, 18.0 feet below crown Flap gate on the waterward end. Slide gate in CMP riser on waterside shoulder. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 2/25/2014					

No Photos

LM Start	7.77	Rating **	M	Issue No.	44
LM End	7.77	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.711436 °	39.711436 °
				-121.937135 °	-121.937135 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31129					
DS_ID:19254					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Debris in inlet pipe, needs cleaning and clearing.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 18.0 feet					
below the crown. Flap gate on the waterward end. Concrete "U"					
headwalls on both ends. Grouted riprap apron on the landward end.					
Grouted riprap spillway on the waterward end. O&M Manual Sac 504,					
May 1965.					
FS Date: 2/25/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Butte County Department of Public Works

Waterway			Bank	Unit Miles
Unit No. 02A Channel Slough			Left	0.26
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	4/25/2016 - 4/25/2016		10/13/2016 - 10/13/2016	
DWR Inspector	Keith Millard		Tariq Chechi	
Accompanied By	Shawn Bates Butte County		Shawn Bates Butte County	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02A Channel Slough	Left	0.26	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.00	Rating **	A	Issue No.	4
LM End	0.00	Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.733077 °	39.733077 °
				-121.930273 °	-121.930273 °
DWR ID	DWR_NA0003_02A_f_2016_4				
Comment Code					
Inspector Comment					
LMA is keeping grass and weeds off of levee slopes.					

Photo 1 of 1 : FA_2016_NA0003_66_4_20161026_00001.jpg



View of the levee crown.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Butte County Department of Public Works

Waterway			Bank	Unit Miles
Unit No. 03 Sycamore and Sheep Hollow Creeks			Right	4.05
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	4/25/2016 - 4/25/2016		10/13/2016 - 10/13/2016	
DWR Inspector	Keith Millard		Tariq Chechi	
Accompanied By	Shawn Bates Butte County		Shawn Bates Butte County	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.05	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.02	Rating **	M	Issue No.	12
LM End	0.02	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.785970 °	39.785970 °
				-121.882797 °	-121.882797 °
DWR ID	DWR_NA0003_03_f_2015_12				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Repair the erosion on both slopes caused by motorcycle traffic.					

Photo 1 of 1 : FA_2016_NA0003_67_12_20160823_00002.jpg



View of the erosion on both slopes caused by motorcycle traffic.

LM Start	0.07	Rating **	M	Issue No.	3
LM End	0.07	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.786068 °	39.786068 °
				-121.881828 °	-121.881828 °
DWR ID	DWR_NA0003_03_s_2012_3				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Repair the erosion on landside slope caused by motorcycle traffic.					

Photo 1 of 1 : FA_2016_NA0003_67_3_20160823_00001.jpg



View of the erosion caused by motorcycles on the land side slope.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.05	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.10	Rating **	M	Issue No.	21
LM End	0.10	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.786195 °	39.786195 °
				-121.881325 °	-121.881325 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:32103
DS_ID:19262
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Slide gate in CMP riser on waterside. The culvert was working during field inspection.
FIELD_STRUCT_DESC: 42-inch CM pipe through the levee, 14 feet below the crown. Flap gate on the waterward end. Slid gate in CM riser on the waterward slope. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.
FS Date: 3/11/2014

LM Start	0.10	Rating **	M	Issue No.	21 (cont)
LM End	0.10	Issue Type +	En	Location *	WS

Photo 1 of 2 : UCIP_FA_2016_32103_58602.jpg



WS view: U type concrete headwall, pipe, and flapgate on levee slope.

Photo 2 of 2 : UCIP_FA_2016_32103_58601.jpg



WS view: U type concrete headwall of CMP culvert on levee slope.
Grouted riprap levee slope and spillway.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.05	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.35	Rating **	M	Issue No.	15
LM End	0.35	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.785704 °	39.785704 °
				-121.877004 °	-121.877004 °
DWR ID	DWR_NA0003_03_f_2016_15				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_67_15_20161019_00022.jpg



View of the overgrown tree along the landside slope.

LM Start	1.96	Rating **	M	Issue No.	22
LM End	1.96	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.781714 °	39.781714 °
				-121.850868 °	-121.850868 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31900 DS_ID:19266 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Needs location confirmation, GPS reading has not taken due to access problem. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 8.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 3/11/2014					

Photo 1 of 1 : UCIP_FA_2016_31900_58189.jpg



Bird's eye view: concrete headwall visible on both sides of the levee.
Grouted riprap spillway on waterside.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.05	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.17	Rating **	M	Issue No.	19
LM End	2.17	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.785290 °	39.785290 °
				-121.844235 °	-121.844235 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:32124
DS_ID:19267
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Pipe is about 4 feet below the crown. Needs cleaning and clearing the culvert.
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 6.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwall on each end. O&M Manual Sac 504, May 1965.
FS Date: 3/7/2014

LM Start	2.17	Rating **	M	Issue No.	19 (cont)
LM End	2.17	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_32124_58625.jpg



WS view: concrete headwall, pipe, and flapgate on levee slope.
Vegetation and mud on outlet box.

Photo 2 of 2 : UCIP_FA_2016_32124_58624.jpg



LS view: U type concrete headwall of CMP culvert on levee slope.
Vegetation on inlet box.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.05	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.22	Rating **	M	Issue No.	24							
LM End	2.22	Issue Type +	En	Location *	LS							
Category	Supplemental		GPS Latitude/Longitude									
			Start	End								
Item	DWR UCIP Field Study		39.785917 °	39.785917 °								
			-121.844502 °	-121.844502 °								
DWR ID												
Comment Code												
Inspector Comment												
FS_ID:41872 DS_ID:19268 EP_NO: 14512 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Need to contact owner to determine status of crossing and install gasoline markers if appropriate. FIELD_STRUCT_DESC: 6-inch steel gas pipeline through the levee, 2 feet below the crown. Paddle marker on landward slope. (Permit No. 14512) FS Date: 3/7/2014												

No Photos

LM Start	3.08	Rating **	M	Issue No.	23							
LM End	3.08	Issue Type +	En	Location *	LS							
Category	Supplemental		GPS Latitude/Longitude									
			Start	End								
Item	DWR UCIP Field Study		39.778016 °	39.778016 °								
			-121.854460 °	-121.854460 °								
DWR ID												
Comment Code												
Inspector Comment												
FS_ID:31901 DS_ID:19269 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs cleaning and clearing the culvert. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 11.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 3/7/2014												

Photo 1 of 2 : UCIP_FA_2016_31901_58194.jpg



WS view: U type concrete headwall, flapgate, and CMP on levee slope.
Needs cleaning and clearing.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.05	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.08	Rating **	M	Issue No.	23 (cont)	
LM End	3.08	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.778016 °	39.778016 °	
				-121.854460 °	-121.854460 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:31901						
DS_ID:19269						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Needs cleaning and clearing the culvert.						
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 11.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.						
FS Date: 3/7/2014						

Photo 2 of 2 : UCIP_FA_2016_31901_58193.jpg



LS view: U type concrete headwall and CMP on levee slope. Soil/mud on inlet box.

LM Start	3.34	Rating **	M	Issue No.	17
LM End	3.34	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.777410 °	39.777410 °
				-121.849627 °	-121.849627 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31864 DS_ID:19271 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs cleaning and clearing the culvert. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 10.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 3/7/2014					

Photo 1 of 2 : UCIP_FA_2016_31864_58069.jpg



WS view: U type concrete headwall, pipe, and flapgate on levee slope. Soil/mud on outlet box. Vegetation debris blocking outlet box.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.05	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.34	Rating **	M	Issue No.	17 (cont)	
LM End	3.34	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.777410 °	39.777410 °	
				-121.849627 °	-121.849627 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:31864						
DS_ID:19271						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Needs cleaning and clearing the culvert.						
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 10.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.						
FS Date: 3/7/2014						

Photo 2 of 2 : UCIP_FA_2016_31864_58068.jpg



LS view: U type concrete headwall and CMP on levee slope. Soil/mud on inlet box.

LM Start	3.38	Rating **	M	Issue No.	14
LM End	3.38	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.777429 °	39.777429 °
				-121.848937 °	-121.848937 °
DWR ID	DWR_NA0003_03_f_2016_14				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_67_14_20161019_00023.jpg



View of a bush along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.05	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.50	Rating **	M	Issue No.	16
LM End	3.50	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.777139 °	39.777139 °
				-121.846769 °	-121.846769 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31856					
DS_ID:19272					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing the culvert.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 9.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 3/7/2014					

LM Start	3.50	Rating **	M	Issue No.	16 (cont)
LM End	3.50	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_31856_58053.jpg



WS view: U type concrete headwall, pipe, and flapgate on levee slope.
Soil/mud on outlet box.

Photo 2 of 2 : UCIP_FA_2016_31856_58052.jpg



LS view: U type concrete headwall and CMP on levee slope. Soil/mud on inlet box.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.05	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.65	Rating **	M	Issue No.	18
LM End	3.65	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.777381 °	39.777381 °
				-121.844052 °	-121.844052 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31851 DS_ID:19273 EP_NO: 14512 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: A 6-inch steel pipe attached to the Cohasset Road Bridge. Not confirmed whether this is a gasoline pipe. FIELD_STRUCT_DESC: 6-inch gas steel pipeline through the levee, 2 feet below the crown. (App. 14512 PG&E, 11/86) FS Date: 3/7/2014					

Photo 1 of 1 : UCIP_FA_2016_31851_58041.jpg



WS view: 6-inch steel pipe attached to Cohasset Road Bridge. Needs confirmation from LMA whether this is a gasoline.

LM Start	3.68	Rating **	M	Issue No.	20
LM End	3.68	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.777662 °	39.777662 °
				-121.843489 °	-121.843489 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32125 DS_ID:19275 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: The culvert was working during the field visit.Needs cleaning and clearing on both ends of the pipe. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 7.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 3/4/2014					

Photo 1 of 2 : UCIP_FA_2016_32125_58629.jpg



WS view: U type concrete headwall, pipe, and flapgate on levee slope. Soil/mud on outlet box. Vegetation debris blocking outlet box.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sycamore and Sheep Hollow Creeks	Right	4.05	10/13/2016 10/13/2016	Tariq Chechi

LM Start	3.68	Rating **	M	Issue No.	20 (cont)
LM End	3.68	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.777662 °	39.777662 °
				-121.843489 °	-121.843489 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32125 DS_ID:19275 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: The culvert was working during the field visit.Needs cleaning and clearing on both ends of the pipe. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 7.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 3/4/2014					

Photo 2 of 2 : UCIP_FA_2016_32125_58628.jpg



LS view: U type concrete headwall and pipe on levee slope. Soil/mud on inlet box. Vegetation debris blocking inlet box.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Butte County Department of Public Works

Waterway			Bank	Unit Miles
Unit No. 04 Sycamore and Dry Creeks			Right	2.86
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			M	
Date of Inspection	4/25/2016 - 4/25/2016		10/13/2016 - 10/13/2016	
DWR Inspector	Keith Millard		Tariq Chechi	
Accompanied By	Shawn Bates Butte County		Shawn Bates Butte County	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.16	Rating **	M	Issue No.	20
LM End	0.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.776526 °	39.776526 °
				-121.848727 °	-121.848727 °
DWR ID	DWR_NA0003_04_f_2016_20				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_68_20_20161019_00036.jpg



View of the vegetation along the landside toe blocking visibility.

LM Start	0.27	Rating **	M	Issue No.	34
LM End	0.27	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.776554 °	39.776554 °
				-121.850730 °	-121.850730 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32026					
DS_ID:19279					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing the culvert.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 10.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 3/7/2014					

Photo 1 of 2 : UCIP_FA_2016_32026_58520.jpg



WS view: concrete headwall and grouted riprap spillway on levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.27	Rating **	M	Issue No.	34 (cont)	
LM End	0.27	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.776554 °	39.776554 °	
				-121.850730 °	-121.850730 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:32026						
DS_ID:19279						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Needs cleaning and clearing the culvert.						
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 10.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end.						
Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.						
FS Date: 3/7/2014						

Photo 2 of 2 : UCIP_FA_2016_32026_58519.jpg



WS view: U type concrete headwall and CMP on levee slope. Mud and vegetation debris on outlet box.

LM Start	0.33	Rating **	M	Issue No.	33
LM End	0.33	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.775926 °	39.775926 °
				-121.850647 °	-121.850647 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32025					
DS_ID:19280					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Slide gate in a CMP riser. Vegetation debris and mud on inlet box.Needs cleaning and clearing the culvert.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee and under the channel, 9.5 feet below the crown. Slide gate in CM pipe riser on the waterward slope. Concrete "U" headwall on the landward end. O&M Manual Sac 504, May 1965.					
FS Date: 3/7/2014					

Photo 1 of 2 : UCIP_FA_2016_32025_58512.jpg



WS view: slide gate in CMP riser on waterside shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.33	Rating **	M	Issue No.	33 (cont)
LM End	0.33	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.775926 °	39.775926 °
				-121.850647 °	-121.850647 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32025					
DS_ID:19280					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Slide gate in a CMP riser. Vegetation debris and mud on inlet box.Needs cleaning and clearing the culvert.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee and under the channel, 9.5 feet below the crown. Slide gate in CM pipe riser on the waterward slope. Concrete "U" headwall on the landward end. O&M Manual Sac 504, May 1965.					
FS Date: 3/7/2014					

Photo 2 of 2 : UCIP_FA_2016_32025_58511.jpg



WS view: inside view of slide gate in CMP riser on waterside shoulder. Debris trapped in the riser.

LM Start	0.35	Rating **	M	Issue No.	32
LM End	0.35	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.775682 °	39.775682 °
				-121.850375 °	-121.850375 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32023					
DS_ID:19281					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing the culvert.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 8.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwall on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 3/7/2014					

Photo 1 of 2 : UCIP_FA_2016_32023_58505.jpg



WS view: U type concrete headwall and CMP on levee slope. Vegetation debris and mud on outlet box. Needs cleaning and clearing.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.35	Rating **	M	Issue No.	32 (cont)	
LM End	0.35	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.775682 °	39.775682 °	
				-121.850375 °	-121.850375 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:32023						
DS_ID:19281						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Needs cleaning and clearing the culvert.						
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 8.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwall on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.						
FS Date: 3/7/2014						

Photo 2 of 2 : UCIP_FA_2016_32023_58504.jpg



LS view: U type concrete headwall and CMP on levee slope. Pebbles and mud on inlet box.

LM Start	0.35	Rating **	M	Issue No.	21
LM End	0.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.775672 °	39.775220 °
				-121.850301 °	-121.849805 °
DWR ID	DWR_NA0003_04_f_2016_21				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_68_21_20161019_00037.jpg



View of the overgrown trees along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.90	Rating **	M	Issue No.	22
LM End	0.90	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.775486 °	39.775486 °
				-121.850606 °	-121.850606 °
DWR ID	DWR_NA0003_04_f_2016_22				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_68_22_20161019_00038.jpg



View of the blackberries blocking visibility and access.

LM Start	0.92	Rating **	M	Issue No.	25	
LM End	0.92	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.775704 °	39.775704 °	
				-121.850901 °	-121.850901 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:32143						
DS_ID:19287						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Needs cleaning and clearing the culvert.						
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 9.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.						
FS Date: 3/7/2014						

Photo 1 of 2 : UCIP_FA_2016_32143_58641.jpg



WS view: U type concrete headwall and CMP on levee slope. Soil/mud on outlet box. Needs cleaning and clearing.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.92	Rating **	M	Issue No.	25 (cont)	
LM End	0.92	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.775704 °	39.775704 °	
				-121.850901 °	-121.850901 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:32143						
DS_ID:19287						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Needs cleaning and clearing the culvert.						
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 9.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.						
FS Date: 3/7/2014						

Photo 2 of 2 : UCIP_FA_2016_32143_58640.jpg



LS view: U type concrete headwall and CMP on levee slope. Vegetation and mud on inlet box.

LM Start	0.92	Rating **	M	Issue No.	27
LM End	0.92	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.775729 °	39.775729 °
				-121.850950 °	-121.850950 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31946 DS_ID:19293 EP_NO: 15950 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Only little gasoline indicator flags found on both sides of the levee and across the creek. FIELD_STRUCT_DESC: 6-inch-diameter high pressure gas main line under both levees and across channel of Dry Creek. 2 feet below the crown. Application No. 15950, 1992. FS Date: 3/7/2014					

Photo 1 of 2 : UCIP_FA_2016_31946_58357.jpg



WS view: little gasline indicator (yellow flags) on both sides of the levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.92	Rating **	M	Issue No.	27 (cont)	
LM End	0.92	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.775729 °	39.775729 °	
				-121.850950 °	-121.850950 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:31946 DS_ID:19293 EP_NO: 15950 Repair Type: Non-Urgent Crossing Status: Indicator Found UCIP Comments: Only little gasoline indicator flags found on both sides of the levee and across the creek. FIELD_STRUCT_DESC: 6-inch-diameter high pressure gas main line under both levees and across channel of Dry Creek. 2 feet below the crown. Application No. 15950, 1992. FS Date: 3/7/2014						

Photo 2 of 2 : UCIP_FA_2016_31946_58356.jpg



WS view: close up view of little gasline indicator.

LM Start	0.94	Rating **	M	Issue No.	26
LM End	0.94	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.775899 °	39.775899 °
				-121.851124 °	-121.851124 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:32144					
DS_ID:19288					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Slide gate in CMP riser on waterside. No access to CMP riser. Needs cleaning and clearing the culvert.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee and under the channel, 9.5 feet below the crown. Slide gate in pipe riser on the waterward slope. Concrete "U" headwall on the landward end. O&M Manual Sac 504, May 1965.					
FS Date: 3/7/2014					

Photo 1 of 2 : UCIP_FA_2016_32144_58644.jpg



LS view: U type concrete headwall of CMP culvert on levee slope. Vegetation debris and mud on inlet box.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Butte County Department of Public Works

View of the fence and trees along the landside toe of the levee.

Page 8 of 16

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	1.04	Rating **	M	Issue No.	23
LM End	1.04	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.776589 °	39.776589 °
				-121.852600 °	-121.852600 °
DWR ID	DWR_NA0003_04_f_2016_23				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_68_23_20161019_00039.jpg



View of the blackberries blocking visibility and access.

LM Start	1.11	Rating **	M	Issue No.	28
LM End	1.11	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.776709 °	39.776709 °
				-121.853932 °	-121.853932 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31963 DS_ID:19289 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs cleaning and clearing the culvert. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 11.0 feet below the flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 3/7/2014					

Photo 1 of 2 : UCIP_FA_2016_31963_58384.jpg



WS view: U type concrete headwall and CMP on levee slope. Vegetation debris and mud on outlet box. Needs cleaning and clearing.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	1.11	Rating **	M	Issue No.	28 (cont)	
LM End	1.11	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.776709 °	39.776709 °	
				-121.853932 °	-121.853932 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:31963 DS_ID:19289 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Needs cleaning and clearing the culvert. FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 11.0 feet below the flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965. FS Date: 3/7/2014						

Photo 2 of 2 : UCIP_FA_2016_31963_58383.jpg



LS view: U type concrete headwall and CMP on levee slope. Vegetation debris and mud on inlet box.

LM Start	1.11	Rating **	U	Issue No.	3
LM End	1.22	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.776760 °	39.777650 °
				-121.854022 °	-121.855687 °
DWR ID	DWR_NA0003_04_s_2012_3				
Comment Code					
FE : Fence					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_68_3_20160823_00003.jpg



View of the fence along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	1.16	Rating **	M	Issue No.	17
LM End	1.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.777128 °	39.777580 °
				-121.854763 °	-121.855612 °
DWR ID	DWR_NA0003_04_f_2015_17				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					
Remove the trees that are overhanging the levee slope.					

Photo 1 of 1 : FA_2016_NA0003_68_17_20160823_00004.jpg



View of the trees overhanging the levee slope.

LM Start	1.27	Rating **	M	Issue No.	2
LM End	1.36	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.778003 °	39.778378 °
				-121.856403 °	-121.857953 °
DWR ID	DWR_NA0003_04_s_2012_2				
Comment Code					
DT : Ditch					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_68_2_20160823_00002.jpg



View of ditch at the landside toe.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Butte County Department of Public Works

LM Start	1.35	Rating **	M	Issue No.	29 (cont)
LM End	1.35	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_31964_58389.jpg



WS view: U type concrete headwall and CMP on levee slope. Vegetation debris and mud in outlet box. Needs cleaning and clearing.

Photo 2 of 2 : UCIP_FA_2016_31964_58388.jpg



LS view: U type concrete headwall and CMP on levee slope. Vegetation debris and mud in inlet box.

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.04	Rating **	U	Issue No.	18
LM End	2.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.781669 °	39.782025 °
				-121.869804 °	-121.870252 °
DWR ID	DWR_NA0003_04_s_2016_18				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trees and shrubbery obscure visibility on landside toe hinge point.					

Photo 1 of 1 : FA_2016_NA0003_68_18_20160823_00005.jpg



View of the vegetation on fence at landside toe.

LM Start	2.15	Rating **	M	Issue No.	30
LM End	2.15	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.782777 °	39.782777 °
				-121.871179 °	-121.871179 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31965					
DS_ID:19291					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing the culvert.					
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 11.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwall on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 3/7/2014					

Photo 1 of 2 : UCIP_FA_2016_31965_58395.jpg



WS view: U type concrete headwall and CMP on levee slope. Vegetation debris and mud in outlet box. Needs cleaning and clearing.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.15	Rating **	M	Issue No.	30 (cont)	
LM End	2.15	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.782777 °	39.782777 °	
				-121.871179 °	-121.871179 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:31965						
DS_ID:19291						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Needs cleaning and clearing the culvert.						
FIELD_STRUCT_DESC: 24-inch CM pipe through the levee, 11.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwall on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.						
FS Date: 3/7/2014						

Photo 2 of 2 : UCIP_FA_2016_31965_58394.jpg



LS view: U type concrete headwall and CMP on levee slope. Vegetation debris and mud in inlet box.

LM Start	2.31	Rating **	C	Issue No.	19
LM End	2.37	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.783092 °	39.783460 °
				-121.874077 °	-121.875205 °
DWR ID	DWR_NA0003_04_s_2016_19				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Moderate vegetation obscuring landside toe.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.47	Rating **	M	Issue No.	31
LM End	2.47	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.784244 °	39.784244 °
				-121.876810 °	-121.876810 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:31966					
DS_ID:19292					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Needs cleaning and clearing the culvert.					
FIELD_STRUCT_DESC: 24-inch CM pipe through levee, 11.0 feet below the crown. Flap gate on the waterward end. Concrete "U" headwalls on both ends. Grouted riprap apron on the landward end. Grouted riprap spillway on the waterward end. O&M Manual Sac 504, May 1965.					
FS Date: 3/7/2014					

LM Start	2.47	Rating **	M	Issue No.	31 (cont)
LM End	2.47	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_31966_58401.jpg



WS view: U type concrete headwall and grouted riprap spillway on levee slope.

Photo 2 of 2 : UCIP_FA_2016_31966_58400.jpg



WS view: U type concrete headwall and CMP on levee slope. Vegetation debris and mud on outlet box. Needs cleaning and clearing.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Sycamore and Dry Creeks	Right	2.86	10/13/2016 10/13/2016	Tariq Chechi

LM Start	2.49	Rating **	M	Issue No.	24
LM End	2.61	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.784408 °	39.785619 °
				-121.877053 °	-121.878604 °
DWR ID	DWR_NA0003_04_f_2016_24				
Comment Code					
DT : Ditch					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_68_24_20161019_00040.jpg



View of a ditch along the landside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Butte County Department of Public Works

Waterway			Bank	Unit Miles
Unit No. 05 Big Chico Diversion			Left	1.85
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	4/25/2016 - 4/25/2016		10/13/2016 - 10/13/2016	
DWR Inspector	Keith Millard		Tariq Chechi	
Accompanied By	Shawn Bates Butte County		Shawn Bates Butte County	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Butte County Department of Public Works

Butte County Department of Public Works

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Big Chico Diversion	Left	1.85	10/13/2016 10/13/2016	Tariq Chechi

LM Start	0.89	Rating **	A/W	Issue No.	6
LM End	0.89	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.764397 °	39.764397 °
				-121.803335 °	-121.803335 °
DWR ID	DWR_NA0003_05_f_2014_6				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberry is not completely blocking the visibility.					

No Photos

LM Start	1.25	Rating **	M	Issue No.	13
LM End	1.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.768621 °	39.768621 °
				-121.807052 °	-121.807052 °
DWR ID	DWR_NA0003_05_f_2016_13				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2016_NA0003_69_13_20161019_00014.jpg



View of the damaged slope by foot traffic.

LM Start	1.28	Rating **	A	Issue No.	10
LM End	1.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			39.769030 °	39.775383 °
				-121.807428 °	-121.814139 °
DWR ID	DWR_NA0003_05_f_2016_10				
Comment Code					
Inspector Comment					
Levee Mile 1.28 to 1.85 is a patrol road and issues related to patrol road should only be documented: e.g. encroachment on the road and crown deficiencies.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Butte County Department of Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Big Chico Diversion	Left	1.85	10/13/2016 10/13/2016	Tariq Chechi

LM Start	1.34	Rating **	M	Issue No.	14
LM End	1.34	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.769761 °	39.769761 °
				-121.808152 °	-121.808152 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:41440 DS_ID:19300 EP_NO: 13368 Repair Type: Non-Urgent Crossing Status: Not Found UCIP Comments: No marker or indicator found. FIELD_STRUCT_DESC: 15-inch concrete sewer line through the levee and Big Chico Diversion channel, 3 feet below the channel. (App. 13368 - Chico Sewer District) FS Date: 3/4/2014					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---